Mak S. Pare-

MEMORANDUM FOR: All NWS Regional Headquarters, Regional Maintenance

Specialists, Electronic Systems Analysts, and Electronics Technicians [Engineering Handbook

(EHB)-13, Series II distribution]

FROM: W/OPS1 - Mark Paese (Acting)

SUBJECT: Transmittal Memorandum for EHB-13 Series II,

Issuance 02-20

1. Material Transmitted:

Engineering Handbook No. 13 Series II, Advanced Weather Interactive Processing System (AWIPS), Section 1.0, AWIPS Information Note 12, Rev C, IBM Linux Workstation Maintenance Concept.

2. Summary:

AWIPS Information Note 12, Rev C, provides IBM support line and Maintenance concept information and updated agency stock numbers for mouse, keyboard, and software. Changes are noted on the left margin.

3. Effect on Other Instructions:

Replace AWIPS Information Note 12, Rev B with this revision.



AWIPS INFORMATION NOTE 12, REV C (for Electronic Systems Analysts)

Maintenance Logistics & Acquisition Division

W/OPS1: FJZ

SUBJECT: IBM Linux Workstation Maintenance Concept

PURPOSE: To provide IBM Support Line Information

AFFECTED SITES: All AWIPS sites that received the IBM Linux workstation.

TECHNICAL SUPPORT: For questions or problems regarding these instructions, please

contact Franz J.G. Zichy at 301-713-1833 x128. For questions on installing software, please contact the NCF at 301-713-9344.

INFORMATION

A. Hardware and Operating System Resolution for Units Received Defective

The IBM workstations are covered by a 3-year, 4-hour response, on-site maintenance.

- 1. In the event sites receive physically damaged IBM workstations, please notify Mr. Jeff Brown at 800-656-0833 x6137 or e-mail him at jjbrown@ibm4pcs.com for replacement parts.
- 2. If after workstation installation, sites require Linux or O/S support, call the IBM support line at 800-237-5511, and provide them with the **IBM customer number 9234207**.

B. Hardware Resolution for Other Types of Failures

Hardware failures attributed to other than shipment are handled through the NRC. If a workstation or monitor fails, call the NCF, open a trouble ticket, and order a new monitor and/or workstation through CLS.

- 1. Use ASN: M100-MLWX for the monitor and ASN: M100-8LWX for the workstation.
- 2. Verify the contents of the box with the new workstation or monitor. Note the keyboard and mouse are not included with the workstation but can be ordered separately. See part E for a parts listing.
- 3. Use the shipping container of the new monitor or workstation to ship the defective unit back to the NRC.
- Once the new workstation is installed and working, call the NCF to close the trouble ticket

NOTE: Before sending the defective unit back to the NRC, verify the contents of the box match the inventory of the items received with the new unit.

C. Software Installation and Equipment Monitoring

- 1. When sites receive instructions from their regional AWIPS focal point to connect the Linux workstations to the AWIPS LAN, install R5.1.2, and the R5.1.2.1 R5.1.2.2 patches.
- 2. Once the software is installed, the Network Control Facility (NCF) will load the IT/Ops agents and templates on each machine to monitor the new workstations.

D. Application Software Resolution

Sites are asked to treat the IBM Linux workstation software issues the same way as the HP-UX workstations. In the event sites experience software problems with their new IBM workstations, call the NCF at 301-713-9344.

NOTE: The NCF is only authorized to monitor nationally deployed Linux boxes; those using lx-1 and lx-2 hostnames.

E. Recovery CDs

The following items for the IBM Linux workstations are stock National Logistics Support Center (NLSC) in Kansas City, MO.

M100-8LWX-1 - PS/2 Mouse

M100-8LWX-2 - PS/2 Keyboard

M100-8LWX-MP1 - Device drivers and enhanced diagnostics CD

M100-8LWX-MP2 - Software selection CD

M100-8LWX-MP3 - Set of 3 IBM Linux workstation recovery CDs

REPORTING INSTRUCTIONS

Failed IBM Linux Workstations sent to NRC must be deactivated from the EMRS database. Submit a WS form A-26 using the equipment code AWLNX, a Type Maintenance code of E and an Action Taken code of B (deactivate). Include maintenance activity associated with the equipment failure on the A-26 used for deactivation. Be sure to inlcude the serial number of the failed unit.

Submit another A-26 to activate the new IBM Linux workstation in the EMRS database. Use an equipment code of AWLNX, a Type Maintenance code of E and an Action Taken code of A (activate). Be sure to include the serial number of the new unit.

Two sample WS Form A-26s are provided as Attachment A-1 and A-2

Mark Paese

Mak S. Pare

Acting Chief, Maintenance, Logistics, and Acquisition Division

Attachment A - WS Form A-26 Samples

Attachment A-1 - WS Form A-26 Sample

WS FORM A-26 (4/94)			WS FORM A 26 (4/94) US. DEPARTMENT OF COMMERCE DOCUMENCE NATIONAL OCEANIC AND ATMERICA ADMINISTRATION NATIONAL WEATHER SERVICE ENGINEERING MANAGEMENT REPORTING SYSTEM MAINTENANCE RECORD Document Number C 49978											
General Information			1. Open Date 3/ 28 / 0	Time 090 (2. Initials JMI	-	Respons O Imm	ediate	•	one) Low Not Applic	able	4. Clos		Time 1300
5. Description AWIPS IBM Linux workstation failed; must be replaced through NLSC.														
Equipment Information			6. Station ID		8. Serial Number 78-R9415			9. TM E			10. AT B		11. How Mal. 401	
1 2. EQUIPMENT OPERATIONAL STATUS TIMES			ly Operational	b. Logistics De	lay Partly	Operation	al c.	All Othe	d. Logistics Delay Not Ope				e. All Other 4:00	
13 Parts Hailure Information													14. Work Load Information	
Block #	a.	ASN		b.	NSN	-		c. TM	d. AT	e. How Mal.	f. Qty.	g. Maint. Hrs.	Туре	Staff Hrs.
1 M100-8LWX							C			R 401 1 3		3:00	a. Routine	
2												b. Non- routine	4:00	
3												c. Travel		
4													d. Misc.	
5													e. Overtin	ıe
Miscellaneous AWIPS Linux workstation determined to have hardware											16. Initials JMM			
17. SPECIAL PURPOSE REPORTING			a. Mod. No.	b. Mod./Ad	t./Deact.Date				d.			e.		·
18. CONFIGURATION MGMT. REPORTING (use as directed)			ASN M100	Vendor Part Number (New Part				rt)		Number (C B-R94		erial Number (New Part) EXAMPLE 123		

Attachment A-2 - WS Form A-26 Sample

WS FORM A -26 (4/94)			U.S. DEPARTMENT OF COMMERCE NATIONAL OCEANIC AND ATMOSPHERIC ADMINISTRATION NATIONAL WEATHER SERVICE OF A O O 7 O													
			ENGINEERING MANAGEMENT REPORTING SYSTEM MAINTENANCE RECORD G 49978													
General 1. Information			Open Date 3 / 29 / ()2	Time 1310	2. Initials JMN		Response O Imme	ediate	•	one) Low Not Applic	able	4. Clos		0 / 02	Time 1315
5. Description Activate new IBM AWIPS Linux workstation in EMRS.																
_qp			6. Station ID 7. Equipment Code AWLNX Example 123 E 10. A					10. AT			ow Mal. 99					
OP	QUIPMENT a. PERATIONAL PATUS TIMES	Fully O	perational	b. Lo	gistics Delay	Partly	Operation	nal c.	All Other		I. Logistic	s Delay	Not Ope	rationa	al e.	. All Other
13. Parts Failure Information										14. Work Load Information						
Block #	a. ASN	1			ь.	NSN			c. TM	d. AT	e. How Mal.	f. Qty.	g. Maint. Hrs.	Тур	ре	Staff Hrs.
1	1													a. 1	Routine	
2															Non- routine	
3														с. Т	Γravel	
4														d . 1	Misc.	0:05
5	_											e. (Overtime			
Miscellaneous			15. Maintenance Comments												16. Initials	
Information			Activate new AWIPS Linux workstation in EMRS.												JMM	
17. SPECIAL PURPOSE REPORTING			a. Mod. No. b. Mod./Act./Deac 3/29/02				Date c.			d.				е.		
18. CONFIGURATION MGMT. REPORTING (use as directed)			ASN			Vendor P	Vendor Part Number (New Part)			Serial Number (Old Part)				Serial Number (New Part)		